

TRUMBULL COUNTY BOARD OF DEVELOPMENTAL DISABILITIES

Policy

Section 9.17

ENGINE IDLE POLICY

It shall be the policy of the Trumbull County Board of Developmental Disabilities to limit the engine idle time of their board-owned vehicles to a maximum of three (3) to five (5) minutes after doing a pre-trip inspection as required by Section 3301-83 of the Ohio Department of Education Pupil Transportation Operation and Safety Rules.

Adopted 1/23/06
Updated 7/24/2012

Reference:
OAC 3301-83-20(O)